

HALE SCHOOL

SHOWER REPAIRS

LOCATION

Wembley Downs, WA

CLIENT

Hale School

PROJECT MANAGER

Marc Cugini

DESCRIPTION

Founded in 1858, Hale School is the oldest private boys' school in Western Australia; the school is a day school and a boarding school.

The shower area of the boarding school presented with multiple issues including failed grout, wall sealant and floor joints. BUSS was engaged to complete the repairs and preventative maintenance to the boarding school showers/shower cubicles.

The works included the removal of the old/failed existing grout from the walls and floors and the supply and application of an epoxy grout to the area, the removal and installation of silicone sealant to the wall to wall joints and the wall to floor joints, followed by the application of a two-coat penetrating sealant to the grouted area. Additionally, all taps and shower hardware were inspected and serviced/replaced as necessary.

PRODUCTS USED

- Sikasil
- Davco Rejuvenation Grout

POINTS OF INTEREST

- Existing tiles and surround were undamaged during the removal of the failed grout; and
- Works completed to tight schedule, during term break.



Fig.1 Front view Hale School



Fig.2 Entrance to shower area



Fig.3 Grouting works in progress



admin@buss.com.au



08 9444 1732



PO Box 163, Floreat WA 6014

