

## BANKWEST SAFETY DEPOSIT VAULT - WATERPROOFING WORKS

### LOCATION

300-306 Murray Street  
Perth, WA

### CLIENT

BankWest

### PROJECT MANAGER

Marc Cugini

### DESCRIPTION

The Facility Manager at BankWest's branch in the newly redeveloped Raine Square, was concerned about a flooding risk, in the event of a fire, due to the fire suppression system installed at the facility. In an effort to mitigate the flooding risk, the Facility Manager engaged the services of BUSS Group to complete waterproofing works to the base of the safety deposit vault at the bank.

October 2017, the BUSS team installed the Sikadur Combiflex system to the vault area. The system has advanced adhesion, is very flexible whilst still maintaining a watertight seal; most suited to this environment.

### PRODUCTS USED

- Sika Combiflex / Hypalon Waterproofing System
- Sika Pro Joint Sealant

### POINTS OF INTEREST

- Works completed with no disruption to banking operations;
- Site personnel required police clearances; and
- Works complete to schedule and on budget.



Image 1: BankWest Plaza, Raine Square



Image 2: Vault area pre-works



Image 3: Vault area upon works completion